

| Diameter x stingning | Total längd | Gänglängd | Mutterlängd |
|----------------------|-------------|-----------|-------------|
| 25 x 5 | 850 | 600 | 70 |
| 25 x 10 | 1600 | 1200 | 95 |
| 32 x 5 | 1800 | 1400 | 86 |
| 32 x 6 | 1600 | 1200 | 88 |
| 32 x 10 | 1800 | 1600 | 125 |
| 32 x 12 | 1800 | 1400 | 126 |
| 32 x 16 | 1200 | 1100 | 114 |
| 40 x 5 | 2200 | 1800 | 94 |
| 40 x 10 | 2200 | 2000 | 138 |
| 40 x 12 | 2050 | 1650 | 166 |
| 40 x 20 | 4000 | 3800 | 150 |
| 40 x 25 | 1347 | 1148 | 140 |
| 50 x 5 | 2200 | 1800 | 110 |
| 50 x 10 | 3300 | 3000 | 168 |
| 50 x 12 | 2400 | 2070 | 190 |
| 50 x 15 | 2400 | 1800 | 150 |
| 50 x 16 | 2800 | 2200 | 201 |
| 50 x 20 | 2400 | 1800 | 156 |
| 50 x 25 | 2680 | 2080 | 155 |
| 63 x 5 | 2000 | 1600 | 94 |
| 63 x 10 | 4400 | 4000 | 173 |
| 63 x 15 | 2400 | 1800 | 205 |
| 63 x 20 | 2400 | 1800 | 178 |